

CFM02.17 - Personnel or tyre fitter positioned in blast path e.g. non remote inflation

Personnel or tyre fitter(s) in the blast path, arising from:

- Inflation of tyre with personnel in proximity
- Known fault delivered to workshop for maintenance

Credible Failure mode is addressed by:

- 🛡️ BI.00.04 Supervisors apply fit for purpose performance management processes
- 🛡️ BI.01.01 Trained, Competent and Authorised Tyre Maintainers
- 🛡️ BI.01.10 Tyre hazard awareness for maintainers
- 🛡️ BI.03.02 Protocols for all aspects of wheel assembly maintenance and tyre repair
- 🛡️ BI.03.03 Safe inflation protocols including lock ring seating checks
- 🛡️ BI.03.11 Protocol in place for smaller tyre (<24"/600mm) inspection and integrity testing