

CFM 1CP-07 Operators or passenger has limb outside cabin while travelling

Worker or passenger has limb or body part protruding outside cabin or travelling location, caused by:

- Unaware or does not understand the requirement for operating LV/HV Vehicles on site (travel routes, vehicle capabilities, critical systems)
- Operator and/or passenger wilful violation

This Credible Failure mode is addressed by:

- 🛡️ BI-01D.01 Trained personnel who are supported by an appropriate and up-to-date training management system
- 🛡️ BI-01P.01 Trained, Competent and Authorised Mobile Equipment Operators
- 🛡️ BI-01S.01 Clear operator performance management expectations supported by an active and consistent performance management process