

CFM 2ES-05 Over speed warning alarm fails to operate

Over speed warning alarm fails to operate, caused by:

- Calibration error
- Component or safety system not working when required

This Credible Failure mode is addressed by:

- 🛡️ BI-01P.20 Skilled and experienced personnel are accountable for maintaining mobile equipment
- 🛡️ BI-02D.53 Operator display specifications are detailed for mobile equipment
- 🛡️ BI-02P.05 Regular checking and maintenance of speed measuring systems
- 🛡️ BI-03S.20 Speed and other operating parameter data send
- 🛡️ BI-05S.05 Appropriate system for scheduled inspections include structured checklists and defect reporting