

# CFM 2ES-06 Speedometer does not indicate actual speed

Speedometer does not indicate actual speed, caused by:

- Calibration error
- Component or safety system not working when required
- Changed to miles/hr from km/hr
- Confusion on dual scale (e.g. Hitachi trucks)

This Credible Failure mode is addressed by:

- 🛡️ BI-02P.05 Regular checking and maintenance of speed measuring systems
- 🛡️ BI-05S.05 Appropriate system for scheduled inspections include structured checklists and defect reporting