

CFM 4TP-08 Light vehicle remains in heavy vehicle blind spot due to intersection approach speeds

Collision at intersection caused by HV not stopping at intersection where LV has right of way, caused by:

- HV is unaware of the presence of LV

This Credible Failure mode is addressed by:

- 🛡️ BI-01P.06 Give way requirements information prepared for mobile equipment operators and pedestrians
- 🛡️ BI-01P.12 Sight lines and blind spots by vehicle type - information prepared for vehicle operators
- 🛡️ BI-03D.01 Road design guidelines set minimum standards for the construction and maintenance of the road network
- 🛡️ BI-03P.03 Expected routes by vehicle type are effectively communicated.