

CFM-MN-30 Recommendations from OEM or Third-Party Supplier not implemented

Inherent design or manufacturing faults not being addressed, caused by:

- Operating sites do not have processes in place to implement recommendations
- Actions/work orders raised following OEM/other supplier alerts are not given priority for addressing in required time frames
- Not identifying that safety alerts and technical bulletins apply to equipment in use on the site.

This Credible Failure mode is addressed by:

- 🛡️ BI-01.52 Skilled and experienced personnel are accountable for selection of mobile equipment
- 🛡️ BI-01.53 Skilled and experienced personnel are accountable for maintaining fire detection and suppression systems on mobile equipment
- 🛡️ BI-02.01 Introduction of equipment to site process
- 🛡️ BI-02.02 Maintenance requirements cover all safety and operational systems on mobile plant
- 🛡️ BI-02.50 Plant Safety Files - requirement to register and track plant components and certificates
- 🛡️ BI-02A.01 Fit for purpose equipment selection processes - General
- 🛡️ BI-04.04 Site change management process apply to the introduction of new types and models of mobile equipment