

# CFM-ER-20 Emergency Responders not called or otherwise delayed

Failure to notify emergency responders, leading to/caused by:

- Workers not calling for assistance - even though required
- Only surface workers available (for an underground fire) and not adequately skilled to affect a response
- Workers panic and fail to raise the alarm when required

Credible Failure mode is addressed by:

- 🛡️ BI-01.39 Alarm and vehicle information panel expected response - information prepared for operators
- 🛡️ BI-05.40 Automatic notification of equipment fire to Emergency Response
- 🛡️ BI-09.01 Emergency Preparedness
- 🛡️ BI-09.03 Strategy for testing, reviewing and maintaining the currency of the emergency response plan
- 🛡️ BI-09B.01 Emergency Response Drills
- 🛡️ BI-09B.02 General Fire Training
- 🛡️ BI-09B.04 Emergency response team fire training
- 🛡️ BI-09B.04 Emergency response team fire training