

CFM02.18 - Tyre inflation failure

Caused by:

- over inflation
- having incompatible components
- flotation tyres (tractor tyres) requirements for different inflation process not identified

Credible Failure mode is addressed by:

- 🛡️ BI.03.02 Protocols for all aspects of wheel assembly maintenance and tyre repair
- 🛡️ BI.03.03 Safe inflation protocols including lock ring seating checks