

CFM02.21 - Pedestrian not detected by the operator of the tyre handler

Tyre handler operator is unaware of the presence of pedestrian in an operational area resulting in a mobile equipment pedestrian interaction caused by:

- Tyre or wheel assembly obscures tyre handler operator vision, and
- Pedestrian not on a defined walking path e.g. takes a short cut
- Authorised pedestrian working in an operational area not detected by mobile equipment operator.

Credible Failure mode is addressed by:

- 🛡 BI.01.10 Tyre hazard awareness for maintainers
- 🛡 BI.03.02 Protocols for all aspects of wheel assembly maintenance and tyre repair
- 🛡 BI.03.08 System in place for managing interfaces between tyre handler operator and tyre service personnel
- 🛡 BI.03.10 Safe and productive tyre handler operation