

## CFM 1CD-03 Incorrect action on vehicle system alarm - not understood

On alarm, operator takes wrong action, caused by:

- Lack of training
- Multiple alarms cause confusion and mistakes
- Operating a range of vehicles with different alarms for same issue

This Credible Failure mode is addressed by:

- 🛡 BI-01D.01 Trained personnel who are supported by an appropriate and up-to-date training management system
- 🛡 BI-01P.01 Trained, Competent and Authorised Mobile Equipment Operators
- 🛡 BI-01P.08 Alarm and vehicle information panel expected response - information prepared for Operators
- 🛡 BI-02D.53 Operator display specifications are detailed for mobile equipment
- 🛡 BI-02T.30 Component alarm or safety device compromise data send