

## CFM 1CS-03 No action taken on over speed alarm

Operator fails to identify and act on over speed warning alarm, caused by:

- Unaware of alarm meaning
- Confusion / misinterpretation from multiple alarms in cab
- Unaware of over speed alarm setting
- No supervisor follow up based on alarm

This Credible Failure mode is addressed by:

- 🛡 BI-01D.01 Trained personnel who are supported by an appropriate and up-to-date training management system
- 🛡 BI-01P.08 Alarm and vehicle information panel expected response - information prepared for Operators
- 🛡 BI-03S.20 Speed and other operating parameter data send
- 🛡 BI-04S.20 Proximity detection data send
- 🛡 BI-05S.03 Hazard and incident reporting process that generates value adding corrective actions