

# CFM-LR-10 Operator does not activate suppression systems or use fire extinguisher in a fire or potential fire situation

Suppression/extinguisher systems not activated, caused by:

- lack of knowledge of requirements
- self-preservation (i.e. evacuate before deploying)
- position of fire suppression manual activation button cannot be accessed (compromised by fire or beyond reach from ground level)
- reluctance to deploy the suppression system (e.g. due to operator's perception of the cost of a deployment or unwanted senior management attention)
- fire extinguisher missing or inoperable
- awkward access to or excessively heavy on-board portable fire extinguisher(s)

Credible Failure mode is addressed by:

- 🛡️ BI-01.01 Trained personnel who are supported by an appropriate and up-to-date training management system
- 🛡️ BI-01.04 Trained, Competent and Authorised Mobile Equipment Operators
- 🛡️ BI-01.39 Alarm and vehicle information panel expected response - information prepared for operators
- 🛡️ BI-09.01 Emergency Preparedness
- 🛡️ BI-09B.02 General Fire Training
- 🛡️ BI-09B.03 Operator Fire Training