

CFM-LR-11 Operator parks/abandons mobile equipment on fire or potentially on in a sub optimal location - unable to extinguish

Poor response/park up of mobile equipment on fire, caused by:

- Lack of knowledge or training
- Self-preservation on the part of the operator
- Limited locations to park machinery that are not going to compromise response efforts (e.g. operating in a restricted access area)

Credible Failure mode is addressed by:

- 🛡️ BI-01.01 Trained personnel who are supported by an appropriate and up-to-date training management system
- 🛡️ BI-01.04 Trained, Competent and Authorised Mobile Equipment Operators
- 🛡️ BI-01.39 Alarm and vehicle information panel expected response - information prepared for operators
- 🛡️ BI-03.02 Operators follow site parking requirements
- 🛡️ BI-04.21 Implemented road design guidelines specify minimum fuel bay, roadway and parking area requirements
- 🛡️ BI-05.02 Effective incident reporting, investigation with effective corrective actions
- 🛡️ BI-09.01 Emergency Preparedness
- 🛡️ BI-09B.01 Emergency Response Drills
- 🛡️ BI-09B.02 General Fire Training