







## **CFM05.09 - Assumed nitrogen fill has oxygen above specification (post HV or lightning)**

Unexpected pyrolysis event

Credible Failure mode is addressed by:

-  BI.01.10 Tyre hazard awareness for maintainers
-  BI.03.22 Effective management of nitrogen where used
-  BI.04.03 TPMS monitors tyre pressure and temperature
-  BI.04.07 Placement of barriers and/or warning devices to prevent unwanted vehicle interactions
-  BI.04.20 Lightning Storm Plan
-  BI.04.52 Nitrogen filled tyres