






CFM09.01 - Quarantine distance inadequate

Emergency scenario planning for equipment fires and other pressurised tyre events is inadequate and advice and actions causes tyre related injuries.

Credible Failure mode is addressed by:

-  BI.01.04 Trained, Competent and Authorised Mobile Equipment Operators
-  BI.01.11 Tyre hazard awareness for equipment operators
-  BI.01.12 Tyre hazard awareness for all personnel
-  BI.04.21 Road design guidelines specify quarantine parking requirements
-  BI.04.25 Protocol for parking up and exiting equipment with potentially compromised tyres