

CFM 2ED-02 Mobile Equipment does not meet standards for lighting, signage and identification markings

Vehicle(s) do not comply with site and corporate standards for lighting, signage and markings, caused by:

- Inadequate vehicle identification number design i.e. size and location of numbers
- Uncontrolled introduction of mobile equipment to site e.g. through contractors
- Inadequate pre-operation inspections and/or maintenance
- Sight lines from operator position impeded (dirty windscreens, poorly sited materials/components, etc.)
- Missing/worn reflective markings and strobe lights.

This Credible Failure mode is addressed by:

- 🛡 BI-00D.01 There is a documented site Traffic Management Plan
- 🛡 BI-00S.01 Senior management review, update, and confirm the Traffic Management Plan as being fit-for-purpose by senior management:
- 🛡 BI-01P.11 Vehicle lights and markings requirements - information prepared for operators
- 🛡 BI-01P.20 Skilled and experienced personnel are accountable for maintaining mobile equipment
- 🛡 BI-02P.01 All safety and operational systems on mobile equipment are maintained
- 🛡 BI-05D.03 Effective contractor management processes
- 🛡 BI-05P.04 Skilled and experienced personnel are accountable for specifying and selecting mobile equipment and mobile equipment components
- 🛡 BI-05P.05 Skilled and experienced personnel are accountable for determining the operating parameters for mobile equipment use
- 🛡 BI-05S.05 Appropriate system for scheduled inspections include structured checklists and defect reporting