

## **CFM 2ES-04 Overload warning system fails is incorrect or absent**

Equipment to provide load information fails or is incorrect, caused by:

- Overload warning system fails when 20% overloaded

This Credible Failure mode is addressed by:

- 🛡️ BI-01P.08 Alarm and vehicle information panel expected response - information prepared for Operators
- 🛡️ BI-02P.01 All safety and operational systems on mobile equipment are maintained
- 🛡️ BI-02S.05 Protocols for the calibration of key measuring equipment