




## **CFM 5SS-03 No aggregated monitoring and response to over speed alarms**

Credible Failure mode is addressed by:

-  BI-01P.07 Site specific travelling speed information prepared for vehicle operators
-  BI-02P.05 Regular checking and maintenance of speed measuring systems
-  BI-03S.20 Speed and other operating parameter data send